


Connection sleeve:


1) Connect Sensitive cable with no-sensitive cable.

Connect to contact (ground) bough cables shields.
Connect to contact (N) bough cables central wires.



2) Seal the contact (N).

Seal the contact (N) with seal tape.



3) Use the foil to shield the connector.



4) Close the connection sleeve.



End sleeve:

1) Connect Sensitive cable with end resistance.



2) Seal the contact.

Seal the contact (N) and end resistance with seal tape.



3) Use the foil to shield the end connection.



4) Close end sleeve.

